



IECEx Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.:	DE/BVS/QAR07.0001/14	Page 1 of 2
QAR Free Ref. No.:	ZQS/E195/23	Status: Issued
Details of change:	No details to be mentioned regarding production of explosion protected equipment.	Date of issue: 2024-02-02
Location(s) audited:	HUMMEL AG Mozartstrasse 2 79183 Waldkirch Germany	Valid until: 2027-02-25
	HUMMEL AG Lise-Meitner-Strasse 2 79211 Denzlingen Germany	Audit date: 2024-01-17
Issuing ExCB:	BVS - DEKRA Testing and Certification GmbH	
Manufacturer:	HUMMEL AG Lise-Meitner-Strasse 2 79211 Denzlingen	
Location of Manufacturer:	Germany	
Product information:	Manufacture and distribution of cable entries, plugs and reducers as well as circular connector for mining and industry	
Type of protection:	Flameproof enclosures "d" Increased safety "e" Intrinsic safety "i" Protection by enclosure "t"	
Related QARs:		
DE/BVS/QAR07.0001/00	DE/BVS/QAR07.0001/01	DE/BVS/QAR07.0001/02
DE/BVS/QAR07.0001/03	DE/BVS/QAR07.0001/04	DE/BVS/QAR07.0001/05
DE/BVS/QAR07.0001/06	DE/BVS/QAR07.0001/07	DE/BVS/QAR07.0001/08
DE/BVS/QAR07.0001/09	DE/BVS/QAR07.0001/10	DE/BVS/QAR07.0001/11
DE/BVS/QAR07.0001/12	DE/BVS/QAR07.0001/13	
Related Certificates (manual insertion)::		
Related Certificates (automatic linking)::		
Related Certificates for previous versions:		
IECEx BVS 07.0019X issue: 0	IECEx BVS 07.0019X issue: 1	IECEx BVS 07.0019X issue: 2
IECEx BVS 07.0020X issue: 0	IECEx BVS 07.0021 issue: 0	IECEx BVS 07.0021 issue: 1
IECEx BVS 07.0022X issue: 0	IECEx BVS 07.0022X issue: 1	IECEx BVS 07.0022X issue: 2
IECEx BVS 10.0078X issue: 0	IECEx BVS 10.0078X issue: 1	IECEx BVS 10.0078X issue: 2
IECEx BVS 11.0064U issue: 0	IECEx BVS 11.0064U issue: 1	IECEx BVS 14.0020X issue: 0
IECEx BVS 14.0020X issue: 1	IECEx BVS 14.0020X issue: 2	IECEx BVS 15.0040X issue: 0
IECEx BVS 15.0040X issue: 1	IECEx BVS 15.0040X issue: 2	IECEx BVS 21.0012X issue: 0
IECEx BVS 21.0086 issue: 0	IECEx BVS 22.0028X issue: 0	IECEx DEK 12.0039X issue: 0
IECEx DEK 12.0039X issue: 1	IECEx DEK 12.0039X issue: 2	IECEx KEM 06.0056 issue: 0
IECEx KEM 06.0056 issue: 1	IECEx KEM 06.0056 issue: 2	IECEx KEM 06.0056 issue: 3
IECEx KEM 06.0056 issue: 4	IECEx KEM 06.0056 issue: 5	IECEx KEM 07.0012 issue: 0
IECEx KEM 07.0012 issue: 1	IECEx KEM 07.0012 issue: 2	IECEx KEM 07.0012 issue: 3
IECEx KEM 07.0012 issue: 4	IECEx KEM 07.0013X issue: 0	IECEx KEM 07.0013X issue: 1
IECEx KEM 07.0013X issue: 2	IECEx KEM 07.0013X issue: 3	IECEx KEM 07.0013X issue: 4
IECEx KEM 07.0013X issue: 5	IECEx KEM 07.0014X issue: 0	IECEx KEM 07.0014X issue: 1
IECEx KEM 07.0014X issue: 2	IECEx KEM 07.0014X issue: 3	IECEx KEM 07.0014X issue: 4
IECEx KEM 07.0014X issue: 5	IECEx SIR 11.0044X issue: 0	



IECEX Quality Assessment Report Summary

QAR Ref. No.: **DE/BVS/QAR07.0001/14**

Page 2 of 2

Comments: